IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors:

U. Reichert et al.

Attorney Docket No: BOEH124931

Patent No:

US 7,205,685 B2

Art Unit: 2834 / Confirmation No.: 2040

Issued:

April 17, 2007

Title:

SOLENOID PLUNGER SYSTEM WITH AN ADJUSTABLE MAGNETIC FLUX

REQUEST FOR CERTIFICATE OF CORRECTION

Seattle, Washington 98101

ATTN:

CERTIFICATE OF CORRECTION BRANCH

COMMISSIONER FOR PATENTS:

Enclosed is a Certificate of Correction, Form PTO 1050, for the above-identified U.S. Letters Patent. The errors in the printed patent listed on the enclosed form occurred at the corresponding locations in the application file listed below:

Column,	Line	Page,	Line
8 (Claim 15,	20 line 3)	9 (Claim 25, (Amendment	4-5 lines 2-3) 12/21/06)
8 (Claim 16,	23 line 3)	9 (Claim 24, (Amendment	2 line 2) 12/21/06)

Since the Certificate of Correction is necessitated by Patent and Trademark Office errors, no fee is required.

Respectfully submitted,

CHRISTENSEN O'CONNOR JOHNSON KINDNESSPLLC

Kevan L. Morgan

Registration No. 42,015

Direct Dial No. 206.695.1712

KLM/lac

LAW OFFICES OF CHRISTENSEN O'CONNOR JOHNSON KINDNESSPLACE 1420 Fifth Avenue Suite 2800 Seattle, Washington 98101 206.682.8100

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,205,685 B2

DATED

April 17, 2007

INVENTOR(S):

U. Reichert et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN	LINE	ERROR
8 (Claim 15,	20 line 3)	"plunger arranged." should readplunger arranged between the solenoid plunger and the first shell
8 (Claim 16,	23 line 3)	delete "between the solenoid plunger and the first shell."

MAILING ADDRESS OF SENDER:

Christensen O'Connor Johnson Kindness^{PLLC} 1420 Fifth Avenue, Suite 2800 Seattle, WA 98101 PATENT NO. US 7,205,685 B2

No. of add'l copies @ 50¢ per page

BOEH\24931173A.DOC